

These homes were identified as testing positive for "elevated levels of chlorinated solvents in the soil gas" at the public presentation of the DEC vapor intrusion study

Approximate Oil Spill Location

McGolrick Park

Vapor Intrusion Sampling Location

DEC Residential Study Area

These homes were identified as having tested positive for "elevated levels of several chemicals" at the public presentation of the DEC vapor intrusion study.

